

Prepared for:

Crown Agents Limited

Prepared by:



1. Introduction

This solar site Physical Survey Report is in line with the Scope of Services defined in the Terms of Reference (TORs). While some of the Healthcare Centers are in the urban area, many of the Primary Healthcare Centers are located in the rural areas and are in deplorable states.

With the exception of certain health centers, the major challenge observed was an absence of road access to very remote centers and low hanging power lines. Difficult road access will cause the heavy vehicles, which will be engaged to deliver the required equipment, to travel through rough terrains.

2. Site Survey Objectives

The objective of this survey is to verify the site survey data provided by SNP and to collect additional data, as required, that will be used for the construction of the proposed solar systems.

The following tools will be used in the solar site survey:

- Compass.
- 100m measuring tape.
- Digital camera.
- Note book
- Mobile Phone with sim cards for MTN, Airtel and Etisalat
- Reporting worksheets

3. Methodology

The site survey was performed by 4 teams and 2 survey personnel per team. The teams used survey worksheets to document observations, record findings, and to make recommendations using the following methodology:

- The available space suitable for siting the solar cabin was measured and recorded on a draft site layout drawing. Future possible use of available space by the PHC was also noted.
- The overall site direction highlighting the North -South direction (using the compass) was taken and recorded.
- All key features were highlighted (trees, bore holes topography etc. of the free space available)
- A detailed sketch of the entire site (the buildings, the roads, the trees, everything present on the site) was completed, the sketch shows the site direction.
- Photographs of all observations were taken and recorded as part of this report. The pictures will be useful for the design team during the design phase.

- The locations of overhead lines, water tank stands, trees etc. were all noted and shown on the detailed sketch.
- The team checked the availability of water supply that will be necessary during the civil construction and for cleaning the PV panels during the O&M stage
- The team checked the availability of internet coverage from mobile company such as MTN. Etisalat, and Airtel.
- The height and clearance of surrounding buildings and structures (to determine shading etc.) was measured and noted for shading analysis.
- Checks were made for shading by high rise buildings or trees and a record of features that could cause obstruction and shading to the proposed PV array for the proposed solar Systems was made.

4. General Observations

- 1. Most of the PHC's are located in very remote areas with poor accessibility, which will cause issues for vehicles to deliver the required equipment.
- 2. Certain PHCs in areas with electricity supply, have low hanging overhead lines which may cause problems when heavy vehicles make deliveries to the site to install equipment. These overhead lines will have to be relocated prior to constructions. See the summary table for details.
- 3. There will be security issues for the proposed solar systems when installed, as many of the PHCs do not have boundary walls.
- 4. There are space constraints and issues of accessibility within PHC in following clinics; PHC Abdu Kwari, PHC Makarfi, Television Garage, Badarawa and Rimin Doko Revisit to the sites are required to finalize the location of the Solar systems in these PHCs. EM-ONE will revisit these sites immediately to carry out new measurements and checks to locate the systems, taking into consideration the space constraints and construction challenges.

5. General Recommendations

From the documented site survey, the following will have to be considered:

- 1. Access roads must be constructed in PHCs with accessibility issues.
- 2. Overhead powerlines must be relocated inside certain PHCs and along the access roads.
- 3. Sites with space constraints must have special designs and considerations during the installation of the solar system.
- 4. Construction of boundary walls or security measures must be taken in PHCs that do not have boundary walls.
- 5. Detailed geotechnical investigation must be carried out for the PHCs to properly design the foundations of the solar system. This should be carried out by the EPC contractor during the construction phase.

- 6. A value range of 100KN/m2 to 400KN/m2 at 1m depth may be used for the foundation design in the bidding stage.
- 7. Certain PHC sites located in vegetative farm lands must have sites cleared.
- 8. In very remote areas, where telecommunication services are not available, alternative telecommunication services must be considered for system remote monitoring.

6. Definitions

- 1. Sandy Soil: Observed soil is very loose.
- 2. Sloppy Surface: Observed surface is not level and may require earth work to level the site, such as: cutting and filling to make it level.
- 3. Flat surface: Site requires minimal earth work like normal site clearing, no cutting and filling required.
- 4. Overhead lines: Distribution Power lines.

7. Attachments.

- a. Site Summary General Summary
- b. Site Survey Issue Summary
- c. Space Comparison
- d. Site-Specific PHC Summary with Site Layout Sketch.

.

APPENDIX

- 1. SITE SUMMARY GENERAL SUMMARY
- 2. SITE SURVEY ISSUE SUMMARY
- 3. SPACE COMPARISON
- 4. SITE-SPECIFIC PHC SUMMARY WITH SITE LAYOUT SKETCH.

| S/No. | PHC | Em | ure pty ace | | e of lable ace | Buil | ny ding ding | No. of Building | Height of tallest | Telecommunication | Site Topography | Remark/Issues |
|-------|-----------------|-------------|-------------------|------|----------------------|------|--------------------|--------------------|-------------------|---|--|---|
| ŕ | | Yes | No | L(m) | B (m) | Yes | No | in PHC | Building (m) | network available | , , | , |
| 1 | BADARAWA PHC | ٧ | | 25 | 23 | | ٧ | 6 | 5 | MTN/AIRTEL/GLO/ETIS ALAT | FLAT SURFACE /WITH LOAMY SOIL OBSERVED | Road access to the free space behind the main PHC building has obstruction by a soak away pit, this may cause issues for heavy vehicles accessing the available space at the back of the PHC main building. |
| 2 | JERE PHC | ٧ | | 28 | 12.9 | | ٧ | 3 | 5 | MTN/GLO | UNEVEN SURFACE /WITH LOAMY SOIL OBSERVED | Telecommunication issues may be experienced due to weak signal reception on the available service providers. Availability of overhead line at the entrance into the PHC may cause a problem to heavy vehicle entering the PHC. |
| 3 | PHC ABDU KWARI | | ٧ | 34 | 10 | | ٧ | 3 | 4 | MTN/AITEL/GLO/ETISA LAT | FLAT SURFACE /WITH LOAMY SOIL OBSERVED | Telecommunication issues may be experienced due to weak signal reception on the available service providers. Availability of overhead line at the entrance into the PHC may cause a problem to heavy vehicle entering the PHC. Site need revisit to check available space |
| 4 | PHC ASSO | ٧ | | 30 | 13 | | ٧ | 2 | 4.5 | GLO/ETISALAT | FLAT SURFACE /WITH LOAMY SOIL | The PHC has no security Boundary wall. |
| 5 | PHC AWON | ٧ | | 76 | 71 | | ٧ | 4 | 5 | MTN, AIRTEL, ETISALAT, GLO & STARCOMS | FLAT SURFACE /WITH LOAMY SOIL OBSERVED | There is an overhead power line (indicated as EP on layout) crossing the PHC that needs to be relocated. Available space is being used for farming. |
| 6 | PHC BADIKO | > | | 24 | 11 | | ٧ | 4 | 5 | MTN/AIRTEL | FLAT SURFACE /WITH LOAMY SOIL OBSERVED | 1. Rough PHC access road |
| 7 | PHC DADDU | ٧ | | 33 | 32 | | > | 5 | 3.7 | MTN/GLO/ETISALAT | FLAT SURFACE /WITH SANDY CLAY SOIL OBSERVED | 1. No boundary wall in the PHC. |
| 8 | PHC DAMA KASUWA | ٧ | | 100 | 40 | | ٧ | 7 | 4.4 | MTN/AIRTEL/GLO | FLAT SURFACE /WITH SANDY STONE SOIL OBSERVED | 1. Boundary wall in the PHC was done half way, the whole front is left open. |

| S/No. | PHC | Em | cure pty ace | Avai | e of lable ace | Any Building Shading | | No. of Building | Height of tallest | Telecommunication | Site Topography | Remark/Issues |
|-------|------------------|-----|--------------------|------|----------------------|----------------------------|----------|--------------------|-------------------|-----------------------------|---|--|
| | | Yes | No | L(m) | B (m) | Yes | No | in PHC | Building (m) | network available | one repognaphy | |
| 9 | PHC DAMAU | ٧ | | 35 | 15 | | ٧ | 1 | 5 | MTN | FLAT SURFACE /WITH MUDDY SOIL | Security Boundary wall available but no No gate into the PHC |
| 10 | PHC DAN ALHAJI | ٧ | | 65 | 38 | | ٧ | 5 | 5 | MTN/GLO | FLAT SURFACE /WITH LOAMY SOIL | |
| 11 | PHC DAN JINJIRI | ٧ | | 20 | 6 | | ٧ | 2 | 4.3 | MTN/AITEL/GLO/ETISA LAT | SLOPED SURFACE /WITH ROCKY SOIL OBSERVED | Gate may need relocation |
| 12 | PHC DANGUZURI | ٧ | | 333 | 100 | | ٧ | 7 | 4 | MTN/AIRTEL | FLAT SURFACE /WITH SANDY SOIL OBSERVED | Boundary wall was done half way. Free space used as farmland. More trees available in the proposed free space. |
| 13 | PHC DANWATA | ٧ | | 44 | 25 | | ٧ | 2 | 4.5 | ETISALAT | FLAT SURFACE /WITH MUDDY SOIL OBSERVED | 1. The PHC has no gate. |
| 14 | PHC FAI | ٧ | | 108 | 40 | | ٧ | 3 | 3.5 | AIRTEL/GLO | FLAT SURFACE /WITH CLAY SOIL OBSERVED | 1. The PHC has no boundary wall. |
| 15 | PHC Galadimawa | ٧ | | 41 | 16 | | \ | 4 | 6 | MTN/ETISALAT | UNEVEN SURFACE /WITH SANDY LOAM SOIL OBSERVED | |
| 16 | PHC GANGARA | ٧ | | 36 | 34 | ٧ | | 4 | 5 | MTN/GLO/ETISALAT | FLAT SURFACE /WITH SANDY LOAM SOIL OBSERVED | |
| 17 | PHC GARU KURAMA | ٧ | | 29 | 15 | | ٧ | 8 | 5 | AIRTEL/GLO | FLAT SURFACE /WITH SANDY SOIL OBSERVED | Narrow access road within the PHC. |
| 18 | PHC GESHERE | ٧ | | 50 | 15 | | ٧ | 1 | 3.5 | AIRTEL/GLO | FLAT SURFACE /WITH LOAMY OBSERVED | 1. The PHC has no boundary wall. |
| 19 | PHC GIDAN TAGWAI | ٧ | | 46 | 25 | | ٧ | 1 | 5 | GLO | FLAT SURFACE /WITH LOAMY OBSERVED | The PHC has no boundary wall. Overhead lines cause obstruction when assessing the site. |
| 20 | PHC GIDAN WAYA | ٧ | | 102 | 30 | | ٧ | 3 | 4 | MTN/AIRTEL/GLO/ETIS ALAT | FLAT SURFACE /WITH SANDY CLAY SOIL OBSERVED | 1. The PHC has no boundary wall. |
| 21 | PHC GWARAJI | ٧ | | 44 | 16 | | ٧ | 1 | 5 | GLO & ETISALAT | • | The PHC has no boundary wall. Free space used for farming. |

| S/No. | PHC | Em | ure pty ace | | e of lable ace | Any Building Shading | | No. of Building | Height of tallest | Telecommunication | Site Topography | Remark/Issues |
|-------|---------------------|-----|-------------------|------|----------------------|----------------------------|----|--------------------|-------------------|--|--|--|
| | | Yes | No | L(m) | B (m) | Yes | No | in PHC | Building (m) | network available | , | |
| 22 | PHC HANWA | ٧ | | 32 | 18 | | ٧ | 2 | 5 | MTN/AIRTEL/GLO/ETIS ALAT | SLOPED SURFACE /WITH ROCKY SOIL OBSERVED | |
| 23 | PHC KADAGE | ٧ | | 23 | 17 | | ٧ | 1 | 5 | GLO | FLAT SURFACE /WITH SANDY SOIL OBSERVED | PHC has no boundary wall. Free proposed space is located in the front of the PHC. |
| 24 | PHC KAMURU (IKUKLU) | ٧ | | 40 | 21 | | ٧ | 3 | 5 | GLO | FLAT SURFACE /WITH SANDY-LOAMY SOIL OBSERVED | Entrance gate is narrow. Overhead lines may cause obstruction by heavy vehicle when entering the PHC. |
| 25 | PHC KASAYA | ٧ | | 45 | 43 | | ٧ | 7 | | AIRTEL/ETISALAT | | PHC has no boundary wall. Free space used as farmland. |
| 26 | PHC KURMIN KOGI | ٧ | | 14 | 10 | | ٧ | 3 | 4 | ETISALAT | FLAT SURFACE /WITH SANDY SOIL OBSERVED | Overhead lines cause obstruction into the PHC. Good posibilities of shading from high rise buildings. The ETISALAT telecommunication has poor reception. |
| 27 | PHC KURMIN-BI | ٧ | | 52 | 17 | | ٧ | 2 | 3.5 | MTN/AIRTEL/GLO/ETIS ALAT | FLAT SURFACE /WITH SANDY-LOAM SOIL OBSERVED | 1. PHC has no boundary wall. |
| 28 | PHC LIKORO | ٧ | | 47 | 16 | ٧ | | 4 | 7 | AIRTEL/GLO/ESTARCO M/VISAFONETISALAT/ | FLAT SURFACE /WITH SANDY SOIL OBSERVED | PHC's entrance gate is narrow for heavy trucks passage. Neighbouring boundary wall will cause obstruction to site for construction vehicle to PHC. |
| 29 | PHC MADAKIYA | ٧ | | 32 | 19 | | ٧ | 3 | 4.4 | MTN/AIRTEL/GLO/ETIS ALAT | FLAT SURFACE /WITH SANDY SOIL OBSERVED | 1. PHC has no boundary wall. |
| 30 | РНС МАН | ٧ | | 39 | 26 | ٧ | | 1 | 5 | GLO/ETISALAT | FLAT SURFACE /WITH SANDY SOIL OBSERVED | |
| 31 | PHC MANCHOCK | ٧ | | 30 | 19 | | ٧ | 5 | 3.6 | MTN/AIRTEL/GLO/ETIS ALAT | FLAT SURFACE /LOAMY CLAY SOIL OBSERVED | PHC has no boundary wall. |

| S/No. | РНС | Em | ure pty ace | ty Availab | | vailable Buildin | | No. of Building | Height of tallest | Telecommunication | Site Topography | Remark/Issues |
|-------|--------------------------------|-----|-------------------|------------|-------|------------------|----|--------------------|-------------------|-----------------------------|--|---|
| | | Yes | No | L(m) | B (m) | Yes | No | in PHC | Building (m) | network available | | |
| 32 | PHC MARO | ٧ | | 55 | 23 | ٧ | ٧ | 2 | 5 | AIRTEL/GLO/ETISALAT | FLAT SURFACE /LOAMY SOIL OBSERVED | There are trees that could cause shading of the installation. |
| 33 | PHC RAFIN GUZA | ٧ | | 24 | 17 | | > | 2 | 3.5 | MTN/AIRTEL/GLO/ETIS ALAT | FLAT SURFACE /LOAMY SOIL OBSERVED | |
| 34 | PHC RIMIN DOKO KAURA WARD | | ٧ | 25 | 14 | | ٧ | 3 | 4.5 | ETISALAT | FLAT SURFACE /LOAMY SOIL OBSERVED | Overhead concrete obstruction at the PHC entrance gate which may prevent heavy truck from gaining access to the PHC. A tree is located at the available proposed free space. |
| 35 | PHC RUZIA | ٧ | | 54 | 50 | | ٧ | 1 | 5 | MTN/AIRTEL/GLO | FLAT SURFACE /LOAMY SOIL OBSERVED | PHC has no boundary wall Airtel telecommunication service is poor. |
| 36 | PHC TASHAN KADE (dandako) | ٧ | | 30 | 14 | | | 2 | 4 | MTN/AIRTEL/GLO/ETIS ALAT | FLAT SURFACE /SANDY SOIL OBSERVED | 1. PHC has no boundary wall |
| 37 | PHC TELEVISION GARAGE | | ٧ | 17 | 10 | | ٧ | 6 | 5 | MTN/AIRTEL/GLO/ETIS ALAT | FLAT SURFACE /SANDY SOIL OBSERVED | PHC has access issues within the PHC for heavy vehicles. |
| 38 | PHC TURAWA | ٧ | | 30 | 19 | | ٧ | 1 | 5 | MTN | FLAT SURFACE /SANDY SOIL OBSERVED | 1. No Space to install the solar system. |
| 39 | PHC ZANGO AYA | ٧ | | 36 | 15 | | ٧ | 7 | 5 | AIRTEL &ETISALAT | SLOPY SURFACE /SANDY SOIL OBSERVED | Obstruction by overhead lines along the access road to the PHC. |
| 40 | PHC MAKARFI (HC Tudun Wada) | | ٧ | 14 | 12 | ٧ | | 3 | 4 | MTN/AIRTEL/GLO/ETIS ALAT | SLOPY SURFACE /SANDY SOIL OBSERVED | PHC is surrounded by built up areas. No boundary wall |

SITE SURVEYED ISSUES

| S/No. | Primary Health care center | No Space | No Boundary Wall | Access Issues | Power line obstruction | Recommendation |
|-------|----------------------------|----------|------------------------|------------------|------------------------|---|
| 1 | BADARAWA PHC | | | ٧ | | Access within the PHC to be repaired (obstruction by Soak away pit needs to be repaired). |
| 2 | JERE PHC | | | | ٧ | Need to Raise higher or relocate obstructing over head line |
| 3 | PHC ABDU KWARI | ٧ | ~ | ٧ | | PHC need revisiting for thorough assesment as the survey space may not be sufficient, also access road may need widening. |
| 4 | PHC ASSO | | ٧ | | | Boundary wall coonstruction is required |
| 5 | PHC AWON | | | | ٧ | Line relocation is required within the PHC |
| 6 | PHC BADIKO | | | ٧ | | Rough access road |
| 7 | PHC DADDU | | ٧ | | | Boundary wall construction is required |
| 8 | PHC DAMA KASUWA | | ٧ | | | Boundary wall needs to be constructed |
| 9 | PHC DAMAU | | ٧ | | | Entrance gate needs to be installed |
| 10 | PHC DAN ALHAJI | | | | | |
| 11 | PHC DAN JINJIRI | | ٧ | ٧ | | Access road clearing is required. Gate may need relocation, need revisit |
| 12 | PHC DANGUZURI | | ٧ | | | Boundary wall needs to be constructed, extra site clearing by removal of trees is required. |
| 13 | PHC DANWATA | | ٧ | | | Entrance gate needs to be installed. |
| 14 | PHC FAI | | ٧ | | | Boundary wall needs to be constructed |
| 15 | PHC Galadimawa | | | | | |
| 16 | PHC GANGARA | | | | | |
| 17 | PHC GARU KURAMA | | | ٧ | | Need to further check the accesibility within the PHC by heavy trucks. |
| 18 | PHC GESHERE | | √ | | | Boundary Wall needs to be constructed |
| 19 | PHC GIDAN TAGWAI | | ٧ | ٧ | | Boundary wall needs to be constructed and power line needs to be relocated |
| 20 | PHC GIDAN WAYA | | V | | | Boundary wall needs to be constructed. |
| 21 | PHC GWARAJI | | ٧ | | | Boundary Wall need to be constructed and additional site clearing. |
| 22 | PHC HANWA | | | | | |
| 23 | PHC KADAGE | | √ | | | Boundary wall needs to be constructed |

SITE SURVEYED ISSUES

| S/No. | Primary Health care center | No Space | No Boundary Wall | Access Issues | Power line obstruction | Recommendation |
|-------|--------------------------------|----------|------------------------|------------------|------------------------|---|
| 24 | PHC KAMURU (IKUKLU) | | | ٧ | | Gate needs to be widened further and overhead line needs to be raised or relocated along the accesss road into the PHC. |
| 25 | PHC KASAYA | | ٧ | | | Boundary wall needs to be constructed and additional works in site clearing |
| 26 | PHC KURMIN KOGI | | | ٧ | ٧ | Overhead lines need to be relocated or raised higher along the acces road to PHC, |
| 27 | PHC KURMIN-BI | | ٧ | | | Boundary Wall need to be constructed. |
| 28 | PHC LIKORO | | | ٧ | | Entrance gate needs to be widened and alternative rout needs to be sought out for. |
| 29 | PHC MADAKIYA | | ٧ | | | Boundary wall needs to be constructed. |
| 30 | PHC MAH | | | | | |
| 31 | PHC MANCHOCK | | √ | | | Boundary wall needs to be constructed |
| 32 | PHC MARO | | | | | Tree cutting will be required to avoid shadding |
| 33 | PHC RAFIN GUZA | | | | | |
| 34 | PHC RIMIN DOKO KAURA WARD | ٧ | | ٧ | | The entrance gate requires widening and trees need to be cut down at the proposed free space. |
| 35 | PHC RUZIA | | ٧ | | | Boundary wall needs to be constructed and the telecommunication networks need to be further checked |
| 36 | PHC TASHAN KADE (dandako) | | ٧ | | | Boundary wall need to be constructed |
| 37 | PHC TELEVISION GARAGE | ٧ | | ٧ | | PHC needs further evaluation on the available access road within the PHC |
| 38 | PHC TURAWA | | ٧ | | | |
| 39 | PHC ZANGO AYA | | | | ٧ | Relocation or raising of over head lines |
| 40 | PHC MAKARFI (HC Tudun Wada) | ٧ | | | | Detailed space analysis required as PHC surrounded by built up areas |

SITE USABLE SPACE COMPARED TO REQUIRED SPACE BASED ON DESIGNED SYSTEMS

| S/N | PHC Clinics | System No. | PV Size (KWp) | Required space(m) | Available free space(m) | Remark |
|-----|---------------------|------------|------------------|------------------------------|----------------------------|--|
| 1 | BADARAWA PHC | 7 | 116.48 | 4No.s 15X12m | 25X23m, & 38X13m | Space located At front and back of PHC |
| 2 | JERE PHC | 5 | 28.08 | 2 No.s of 15X12m | 28X12.9m | At the Back of PHC and to the right over the building, need access road to the back. |
| 3 | PHC ABDU KWARI | 4 | 28.08 | 15mX12m | 34X10m | located at the right side of the main building need revisit |
| 4 | PHC ASSO | 1 | 13.26 | 17X5m | 30X13m | In front of PHC main building |
| 5 | PHC AWON | 4,4,4,4 | 112.32 | 4 No.s 15X12m | 76X71m | Right side of the main building, behind the staff quarters |
| 6 | PHC BADIKO | 5 | 28.08 | 2No.s 15X12m | 24X11m | In front of the PHC main Building |
| 7 | PHC DADDU | 4,4,4 | 84.24 | 3 No.s 15X12m | 33X22m | Behind the general ward of PHC. |
| 8 | PHC DAMA KASUWA | 6 | 84.24 | 3No.s 15X12m | 100X40m | In front of the main building in the PHC. |
| 9 | PHC DAMAU | 4 | 28.08 | 15X12m | 35X15m | By the right of the main PHC building. |
| 10 | PHC DAN ALHAJI | 6 | 84.24 | 3 No.s 15X12m | 65X38m | By the right side of the old clinic building. |
| 11 | PHC DAN JINJIRI | 1 | 13.26 | 17X5m | 20X6m | In front of the Main Building (gate may need relocation) |
| 12 | PHC DANGUZURI | 4 | 28.08 | 15X12m | 333X100m | Open space behind the clinic and some in front of PHC |
| 13 | PHC DANWATA | 1 | 13.26 | 17X5m | 44X25m | Open space in front of PHC |
| 14 | PHC FAI | 1 | 13.26 | 17X5m | 108X40m | In front of the main clinic |
| 15 | PHC Galadimawa | 4,4, | 56.16 | 2No.s 15X12m | 41X16m | In front of the PHC |
| 16 | PHC GANGARA | 6 | 84.24 | 3No.s 15X12m | 36X34m | Open space to the left and front of PHC |
| 17 | PHC GARU KURAMA | 4,4 | 56.16 | 4 No.s 15X12m | 29X15m | Beside the old quarters |
| 18 | PHC GESHERE | 1,4 | 41.34 | 1No.s 17X5m, 1No.s 15X12m | 50X15m | To the right of the PHC |
| 19 | PHC GIDAN TAGWAI | 4 | 28.08 | 15X12m | 46X25m | To the right of the PHC |
| 20 | PHC GIDAN WAYA | 6 | 84.24 | 3 No.s 15X12m | 102X30m | Behind the PHC |
| 21 | PHC GWARAJI | 4 | 28.08 | 15X12m | 44X16m & 32X15m | At the front and to the right of the PHC |
| 22 | PHC HANWA | 3 | 23.40 | 18X9m | 32X18m | Behind the PHC |
| 23 | PHC KADAGE | 4 | 28.08 | 15X12m | 23X17m | In front of the PHC |
| 24 | PHC KAMURU (IKUKLU) | 4,4 | 56.16 | 2No.s 15X12m | 40X21m | To the left of the PHC |
| 25 | PHC KASAYA | 3 | 23.40 | 18X9m | 45X43m & 48X19m | Behind the ward and by the right of the PHC |
| 26 | PHC KURMIN KOGI | 2 | 21.06 | 15X9m | 14X10m | In front of PHC |
| 27 | PHC KURMIN-BI | 2 | 21.06 | 15X9m | 52X17m | In front of PHC |
| 28 | PHC LIKORO | 4,4 | 56.16 | 4 No.s 15X12m | 47X16m | To the right of the PHC |
| 29 | PHC MADAKIYA | 1 | 13.26 | 17X5m | 32X19m | In front of PHC |
| 30 | PHC MAH | 1 | 13.26 | 17X5m | 39X26m | By the left of the PHC |
| 31 | PHC MANCHOCK | 4,4 | 56.16 | 4 No.s 15X12m | 30X19m | Behind the clinic |
| 32 | PHC MARO | 3 | 23.40 | 18X9m | 55X23m | Left of the PHC |

| 33 | PHC RAFIN GUZA | 5 | 28.08 | 2No.s 15X12m | 26X13m & 24X17m | In front and behind the PHC |
|----|-----------------------------|-----|-------|---------------|-----------------|---|
| 34 | PHC RIMIN DOKO KAURA WARD | 4,4 | 56.16 | 4 No.s 15X12m | 25X14m | Need Re-visit |
| 35 | PHC RUZIA | 2 | 13.26 | 15X9m | 54X50m & 50X39m | Left and right of the PHC building |
| 36 | PHC TASHAN KADE (dandako) | 3 | 23.40 | 18X9m | 30X14m & 36X8m | In front and to the right of the PHC |
| 37 | PHC TELEVISION GARAGE | 6 | 84.24 | 3 No.s 15X12m | 17X10m & 13X7m | At the right and left between main building and staff quarters need revisit |
| 38 | PHC TURAWA | 1 | 13.26 | 17X5m | 30X19m | Right of the PHC main Building |
| 39 | PHC ZANGO AYA | 6 | 84.24 | 3 No.s 15X12m | 36X15m & 25X13m | Open space behind the quarters and to the right of the quarters |
| 40 | PHC MAKARFI (HC Tudun Wada) | 6 | 84.24 | 3 No.s 15X12m | 14X12m | In front of PHC, need revisit |

KADUNA SOLAR SITE SPECIFIC SURVEY REPORTS FOR 40 CLINICS IN KADUNA STATE

SUMMARY FOR BADARAWA PHC


This summary report is based on the findings of the site survey team of EM-ONE on September 1, 2015.

| Secure Empty | Size of avai | lable space | Building | Number of buildings in | Height of tallest | | |
|--------------|------------------|-------------|-----------------|------------------------|-------------------|--|--|
| Space | L (m) | B (m) | Shading | PHC | building (m) | | |
| Yes | 25 | 23 | No | 6 | 5 | | |
| Telecommu | unication networ | k available | Site Topography | | | | |
| MTN/ | AIRTEL/GLO/ETIS | ALAT | FLAT SURFACE | /WITH LOAMY SO | IL OBSERVED | | |

Notes

- 1. Available space for the installation of a proposed solar system is located at the front and back of the PHC building.
- 2. Access to the available space behind the main PHC building is obstructed by a soak away pit. This will cause access problems for heavy vehicles.

- 1. The soak away pit obstructing the available space must be reinforced.
- 2. The available space may be used for the installation of a solar system.



SUMMARY FOR JERE PHC


This summary report is based on the findings of the site survey team of EM-ONE on September 1, 2015.

| Secure Empty | Size of avai | lable space | Building | Number of buildings in | Height of tallest | |
|--------------|------------------|-------------|-----------------|------------------------|-------------------|--|
| Space | L (m) | B (m) | Shading | PHC | building (m) | |
| Yes | 28 | 12 | No | 3 | 5 | |
| Telecommu | ınication networ | k available | Site Topography | | | |
| | MTN/GLO | | UNEVEN SURFAC | CE /WITH LOAMY S | OIL OBSERVED | |

Notes

- 1. Due to weak signal reception at the PHC, there will be telecommunication issues.
- 2. Overhead lines at the entrance of the PHC will cause problems for heavy vehicles entering the PHC.

- 1. Alternative telecommunication services must be considered for system remote monitoring.
- 2. Overhead powerlines must be relocated or raised higher for vehicle access.



SUMMARY FOR ABDU KWARI PHC


This summary report is based on the findings of the site survey team of EM-ONE on September 1, 2015.

| Secure Empty | Size of avai | lable space | Building | Number of buildings in | Height of tallest | | |
|--------------|------------------|-------------|-----------------|------------------------|-------------------|--|--|
| Space | L (m) | B (m) | Shading | PHC | building (m) | | |
| No | 34 | 10 | No | 3 | 4 | | |
| Telecommu | unication networ | k available | Site Topography | | | | |
| MTN/ | GLO/AIRTEL/ETIS | ALAT | FLAT SURFACE | /WITH LOAMY SO | IL OBSERVED | | |

Notes

- 1. Weak signal reception at this PHC will cause telecommunication problems of the available service providers.
- 2. Overhead powerlines hanging at the entrance into the PHC may cause problems for heavy vehicles entering the PHC.

- 1. Alternative telecommunication services must be considered for system remote monitoring.
- 2. Overhead lines must be relocated or raised higher for ease of vehicle access.



SUMMARY FOR ASSO PHC

This summary report is based on the findings of the site survey team of EM-ONE on September 1, 2015.


| Secure Empty | Size of avai | lable space | Building | Number of buildings in | Height of tallest | | |
|--------------|------------------|-------------|-----------------|------------------------|-------------------|--|--|
| Space | L (m) | B (m) | Shading | PHC | building (m) | | |
| Yes | 30 | 13 | No | 2 | 4.5 | | |
| Telecommu | ınication networ | k available | Site Topography | | | | |
| | GLO/ETISALAT | | FLAT SURFACE | /WITH LOAMY SO | IL OBSERVED | | |

Notes

1. This PHC has no boundary wall.

Recommendations

1. Boundary wall must be constructed to secure PHC and installation.



SUMMARY FOR AWON PHC


This summary report is based on the findings of the site survey team of EM-ONE on September 1, 2015.

| Secure Empty Space | Size of available space | | Building | Number of buildings in | Height of tallest |
|-------------------------------------|-------------------------|--|----------|------------------------|-------------------|
| | L (m) | B (m) | Shading | PHC | building (m) |
| Yes | 76 | 71 | No | 4 | 5 |
| Telecommunication network available | | Site Topography | | | |
| MTN/GLO/ETISALAT/STARCOMS | | FLAT SURFACE /WITH LOAMY SOIL OBSERVED | | IL OBSERVED | |

Notes

- 1. Overhead powerline crossing the PHC must be relocated (indicated as EP on layout)
- 2. Available space is used for farming.

- 1. Overhead powerlines must be relocated.
- 2. Available space must be cleared of vegetation.



SUMMARY FOR BADIKO PHC


This summary report is based on the findings of the site survey team of EM-ONE on September 1, 2015.

| Secure Empty Space | Size of avai | lable space | Building | Building Number of buildings in | |
|-------------------------------------|--------------|-------------|-----------------|---------------------------------|-------------------------|
| | L (m) | B (m) | Shading | PHC | tallest building (m) |
| Yes | 24.46 | 11.65 | No | 4 | 5 |
| Telecommunication network available | | | Site Topography | | |
| MTN/AIRTEL | | | FLAT SURFACE | /WITH LOAMY SO | IL OBSERVED |

Notes

1. Access road to PHC is rough terrain.

- 1. Access road must be repaired.
- 2. Carport design proposed in the front of the PHC.



SUMMARY FOR DADDU PHC

This summary report is based on the findings of the site survey team of EM-ONE on September 1, 2015.


| Secure Empty Space | Size of available space | | Building | Number of buildings in | Height of tallest |
|-------------------------------------|-------------------------|-------|---|------------------------|-------------------|
| | L (m) | B (m) | Shading | PHC | building (m) |
| Yes | 35.7 | 27.5 | No | 5 | 3.7 |
| Telecommunication network available | | | Site Topography | | |
| MTN/GLO/ETISALAT | | | FLAT SURFACE /WITH SANDY CLAY SOIL OBSERVED | | CLAY SOIL |

Notes

1. This PHC has no boundary wall.

Recommendations

1. Boundary wall must be constructed to secure the installed system.



SUMMARY FOR DAMAKASUWA PHC

This summary report is based on the findings of the site survey team of EM-ONE on September 1, 2015.


| Secure Empty Space | Size of available space | | Building | Number of buildings in | Height of tallest |
|-------------------------------------|-------------------------|-------|--|------------------------|-------------------|
| | L (m) | B (m) | Shading | PHC | building (m) |
| Yes | 100 | 40 | No | 7 | 4.4 |
| Telecommunication network available | | | Site Topography | | |
| MTN/GLO/AIRTEL | | | FLAT SURFACE /WITH SANDY STONE SOIL OBSERVED | | TONE SOIL |

Notes

1. Boundary wall in the PHC is not complete with front of wall missing.

Recommendations

1. Boundary wall must be completed to secure installation and PHC.



SUMMARY FOR DAMAU PHC

This summary report is based on the findings of the site survey team of EM-ONE on September 1, 2015.


| Secure Empty Space | Size of available space | | Building | Number of buildings in | Height of tallest |
|-------------------------------------|-------------------------|-------|-----------------|------------------------|-------------------|
| | L (m) | B (m) | Shading | PHC | building (m) |
| Yes | 35 | 15 | No | 1 | 5 |
| Telecommunication network available | | | Site Topography | | |
| MTN | | | FLAT SURFACE | /WITH MUDDY SO | IL OBSERVED |

Notes

1. Boundary wall in the PHC available but is missing an entrance gate.

Recommendations

1. Entrance gate must be constructed to secure installation and PHC.




SUMMARY FOR DAN ALHAJI PHC

This summary report is based on the findings of the site survey team of EM-ONE on September 1, 2015.

| Secure Empty Space | Size of available space | | Building | Number of buildings in | Height of tallest |
|-------------------------------------|-------------------------|-------|-----------------|------------------------|-------------------|
| | L (m) | B (m) | Shading | PHC | building (m) |
| Yes | 65 | 38 | No | 5 | 5 |
| Telecommunication network available | | | Site Topography | | |
| MTN/GLO | | | FLAT SURFACE | /WITH LOAMY SO | IL OBSERVED |

Notes



SUMMARY FOR DAN JINJIRI PHC


This summary report is based on the findings of the site survey team of EM-ONE on September 1, 2015.

| Secure Empty Space | Size of availal | ble free space | Building Number of buildings in | | Height of tallest |
|-------------------------------------|-----------------|----------------|---------------------------------|-----------------|-------------------|
| | L (m) | B (m) | Shading | PHC | building (m) |
| Yes | 20 | 10 | No | 7 | 4 |
| Telecommunication network available | | | Site Topography | | |
| MTN/AIRTEL | | | FLAT SURFACE | /WITH SANDY SOI | L OBSERVED |

Notes:

- 1. Boundary wall is not complete.
- 2. Available space is used for farming.
- 3. Available space has trees.

- 1. Boundary Wall must be completed for security.
- 2. Available space used for farming must be cleared of vegetation for a solar system to be installed.
- 3. Trees will cause obstruction and shading and must be cut down.



SUMMARY FOR DAN GUZURI PHC


This summary report is based on the findings of the site survey team of EM-ONE on September 1, 2015.

| Secure Empty Space | Size of available free space | | Building | Number of buildings in | Height of tallest |
|-------------------------------------|------------------------------|-------|----------|------------------------|-------------------|
| | L (m) | B (m) | Shading | PHC | building (m) |
| Yes | 333 | 100 | No | 7 | 4 |
| Telecommunication network available | | | | Site Topography | |
| | MTN/AIRTEL | | | /WITH SANDY SOI | L OBSERVED |

Notes:

- 1. Boundary wall is not complete.
- 2. Available space is used for farming.
- 3. Available space has trees.

- 1. Boundary Wall must be completed for security.
- 2. Available space used for farming must be cleared of vegetation for a solar system to be installed.
- 3. Trees will cause obstruction and shading and must be cut down.



SUMMARY FOR DAN WATA PHC

This summary report is based on the findings of the site survey team of EM-ONE on September 1, 2015.


| Secure Empty Space | Size of available free space | | Building | Number of buildings in | Height of tallest |
|-------------------------------------|------------------------------|-------|----------|------------------------|-------------------|
| | L (m) | B (m) | Shading | PHC | building (m) |
| Yes | 44 | 25 | No | 2 | 4.5 |
| Telecommunication network available | | | | Site Topography | |
| | ETISALAT | | | /WITH MUDDY SO | IL OBSERVED |

Notes:

1. This PHC has no gate.

Recommendations:

1. Entrance gate must be provided to secure the facility.



SUMMARY FOR FAI PHC

This summary report is based on the findings of the site survey team of EM-ONE on September 1, 2015.


| Secure Empty Space | Size of available free space | | Building | Number of buildings in | Height of tallest |
|-------------------------------------|------------------------------|-------|-------------|------------------------|-------------------|
| | L (m) | B (m) | Shading | PHC | building (m) |
| Yes | 108 | 40 | No | 3 | 3.5 |
| Telecommunication network available | | | | Site Topography | |
| AIRTEL/GLO | | | FLAT SURFAC | E /WITH CLAY SOIL | . OBSERVED |

Notes:

1. This PHC has no boundary wall.

Recommendations:

1. Boundary wall must be constructed to secure facility.




SUMMARY FOR GALADIMAWA PHC

This summary report is based on the findings of the site survey team of EM-ONE on September 1, 2015.

| Secure Empty Space | Size of available free space | | Building | Number of buildings in | Height of tallest |
|-------------------------------------|------------------------------|-------|-------------|------------------------------|-------------------|
| | L (m) | B (m) | Shading | PHC | building (m) |
| Yes | 41 | 16 | No | 4 | 6 |
| Telecommunication network available | | | | Site Topography | |
| MTN/ETISALAT | | | UNEVEN SURF | FACE /WITH SANDY OBSERVED | LOAM SOIL |

Notes:




SUMMARY FOR GANGARA PHC

This summary report is based on the findings of the site survey team of EM-ONE on September 1, 2015.

| Secure Empty Space | Size of available free space | | Building | Number of buildings in | Height of tallest |
|-------------------------------------|------------------------------|-------|------------|------------------------------|-------------------|
| | L (m) | B (m) | Shading | PHC | building (m) |
| Yes | 36 | 34 | No | 4 | 5 |
| Telecommunication network available | | | | Site Topography | |
| MTN/ETISALAT/GLO | | | FLAT SURFA | CE /WITH SANDY L OBSERVED | OAM SOIL |

Notes:



SUMMARY FOR GARU KURAMA PHC

This summary report is based on the findings of the site survey team of EM-ONE on September 1, 2015.


| Secure Empty Space | Size of available free space | | Building | Number of buildings in | Height of tallest |
|-------------------------------------|------------------------------|-------|----------|------------------------|-------------------|
| | L (m) | B (m) | Shading | PHC | building (m) |
| Yes | 29 | 15 | No | 8 | 5 |
| Telecommunication network available | | | | Site Topography | |
| | AIRTEL/GLO | | | /WITH SANDY SOI | L OBSERVED |


Notes:

1. Access road to PHC is narrow.

Recommendations:

1. Alternative access to PHC must be established for material and equipment drop off.





SUMMARY FOR GESHERE PHC

This summary report is based on the findings of the site survey team of EM-ONE on September 1, 2015.


| Secure Empty Space | Size of available free space | | Building | Number of buildings in | Height of tallest |
|-------------------------------------|------------------------------|-------|----------|------------------------|-------------------|
| | L (m) | B (m) | Shading | PHC | building (m) |
| Yes | 50 | 15 | No | 1 | 3.5 |
| Telecommunication network available | | | | Site Topography | |
| | AIRTEL/GLO | | | CE /WITH LOAMY (| OBSERVED |

Notes:

1. This PHC has no boundary wall.

Recommendations:

1. Boundary wall must be completed to secure installations and the PHC.



SUMMARY FOR GIDAN TAGWAI PHC


This summary report is based on the findings of the site survey team of EM-ONE on September 1, 2015.

| Secure Empty Space | Size of available free space | | Building | Number of buildings in | Height of tallest |
|-------------------------------------|------------------------------|-------|------------|------------------------|-------------------|
| | L (m) | B (m) | Shading | PHC | building (m) |
| Yes | 46 | 25 | No | 1 | 5 |
| Telecommunication network available | | | | Site Topography | |
| GLO | | | FLAT SURFA | CE /WITH LOAMY (| OBSERVED |

Notes:

- 1. This PHC has no boundary wall.
- 2. Overhead lines will cause obstruction when accessing the site.

- 1. Boundary wall must be completed to secure installations and the PHC.
- 2. Overhead lines must be raised higher or relocated.



SUMMARY FOR GIDAN WAYA PHC

This summary report is based on the findings of the site survey team of EM-ONE on September 1, 2015.


| Secure Empty Space | Size of available free space | | Building | Number of buildings in | Height of tallest |
|-------------------------------------|------------------------------|-------|------------|-------------------------------|-------------------|
| | L (m) | B (m) | Shading | PHC | building (m) |
| Yes | 102 | 30 | No | 3 | 4 |
| Telecommunication network available | | | | Site Topography | |
| MTN/AIRTEL/ETISALAT/GLO | | | FLAT SURFA | ACE /WITH SANDY (OBSERVED | CLAY SOIL |

Notes:

1. This PHC has no boundary wall.

Recommendations:

1. Boundary wall must be completed to secure installations and the PHC.



SUMMARY FOR GWARAJI PHC


This summary report is based on the findings of the site survey team of EM-ONE on September 1, 2015.


| Secure Empty Space | Size of available free space | | Building | Number of buildings in | Height of tallest |
|-------------------------------------|------------------------------|-------|--------------|------------------------|-------------------|
| | L (m) | B (m) | Shading | PHC | building (m) |
| Yes | 40 | 16 | No | 1 | 5 |
| Telecommunication network available | | | | Site Topography | |
| ETISALAT/GLO | | | FLAT SURFACE | /WITH LOAMY SO | IL OBSERVED |

Notes:

- 1. This PHC has no boundary wall.
- 2. Available space is used for farming.

- 1. Boundary wall must be completed to secure installations and the PHC.
- 2. Available space must be cleared of vegetation for system installation.





HANWA PHC LAYOUT

| | PF | PROJECT NAME | | | KADU | NA SO | LAR | PROJECT |
|-----------------|--------------|--------------------|---------|--|------------|--------|--------|---------|
| rs | RE | REFERENCE DRAWING: | | | | | | |
| ETAI | DRAWING NO: | | | | | | | |
| ING | TI | TİTLE: | | | HA | NWA PH | IC LAY | OUT |
| DRAWING DETAILS | DESCRIPTION: | | | | | | | |
| ٥ | D | DRAWN: | | | | | | |
| | CI | HEC | KED BY: | | | | | |
| | D. | DATE: | | | Sept. 2015 | | | |
| | NO | | NAME | | | DAT | E | |
| SN | Α | | | | | | | |
| REVISIONS | В | | | | | | | |
| Ä | С | | | | | | | |
| | D | | | | | | | |
| SHE | ET NO |): | 1 | | TOTAL S | HEETS: | | 1 |

| EGEND: | |
|--------|--|
|--------|--|

| LE | GEND |
|----------------------|-------------------|
| ВН | BORE HOLE |
| Tr | TREE |
| \triangleright_{P} | POLE |
| CF | CONCRETE FLOOR |
| SA | SOAK AWAY |
| SH | SECURITY HOUSE |
| | |

| APPROVED | APPROVED WITH COMMENTS |
|--------------|------------------------|
| NOT APPROVED | FOR INFORMATION |
| FOR APPROVAL | |

SUMMARY FOR HANWA PHC

This summary report is based on the findings of the site survey team of EM-ONE on September 1, 2015.

| Secure Empty | Size of available free space | | Building | Number of buildings in | Height of tallest |
|-------------------------------------|------------------------------|-------|---------------|------------------------|-------------------|
| Space | L (m) | B (m) | Shading | PHC | building (m) |
| No | 32 | 18 | No | 2 | 5 |
| Telecommunication network available | | | | Site Topography | |
| MTN/AIRTEL/ETISALAT/GLO | | | SLOPED SURFAC | CE /WITH ROCKY SO | OIL OBSERVED |

Notes:

1. Available space for solar system installation is 32m x 18m.

SUMMARY FOR KADAGE PHC

This summary report is based on the findings of the site survey team of EM-ONE on September 1, 2015.


| Secure Empty Space | Size of available free space | | Building | Number of buildings in | Height of tallest |
|-------------------------------------|------------------------------|-------|--------------|------------------------|-------------------|
| | L (m) | B (m) | Shading | PHC | building (m) |
| Yes | 23 | 17 | No | 1 | 5 |
| Telecommunication network available | | | | Site Topography | |
| GLO | | | FLAT SURFACE | /WITH SANDY SOI | L OBSERVED |

Notes:

- 1. This PHC has no boundary wall.
- 2. Available space is located in front of the PHC.

Recommendations:

1. Boundary wall must be constructed to secure installation and PHC.



SUMMARY FOR KAMURU IKULU PHC


This summary report is based on the findings of the site survey team of EM-ONE on September 1, 2015.

| Secure Empty | Size of available free space | | Building | Number of buildings in | Height of tallest | |
|--------------|-------------------------------------|-------|-------------|-------------------------------|-------------------|--|
| Space | L (m) | B (m) | Shading | PHC | building (m) | |
| Yes | 40 | 21 | No | 3 | 5 | |
| Telecommu | Telecommunication network available | | | Site Topography | | |
| GLO | | | FLAT SURFAC | CE /WITH SANDY-LO OBSERVED | DAMY SOIL | |

Notes:

- 1. Entrance gate is narrow.
- 2. Overhead powerlines will cause obstruction for heavy vehicles when entering the PHC.

- 1. Entrance gate must be expanded.
- 2. Overhead powerlines must be relocated or raised higher.



| | | | | KADU | NA SOLAF | PROJECT |
|-----------------|--------|-----------------|---------------|------------------------------|---------------------------|---------|
| | PRO | JECT NAME | | 10.50 | TOTAL OCE A | |
| AILS | | RENCE DE | RAWING: | | | |
| DRAWING DETAILS | | WING NO: | | | AMUDU DUC I | AVOUT |
| MIN | TITL | E: CRIPTION: | | | AMURU PHC I | AYOUT |
| DR/ | DRA | | | | | |
| | | CKED BY: | | | | |
| | DATI | | | Sept. | 2015 | |
| | NO | NAME | | Sept. | DATE | |
| Š | A | | | | | |
| REVISIONS | В | | | | | |
| Æ | С | | | | | |
| | D | | | | | |
| SHE | ET NO: | | 1 | TOTAL SI | HEETS: | 1 |
| | | | | | | |
| | | | LE | GEN | D | |
| | | | LE W | WEL | | |
| | | | | WEL | L K | |
| | | | W | SOAI AWA | X Y ITY | |
| | | | W SA | SOAI AWA SECUR | K Y ITY SE | |
| | | | W SA SH | SOAI AWA SECUR HOUS | K Y ITY SE ET | |

NOT APPROVED

FOR APPROVAL

FOR INFORMATION

SIGNATURE / STAMP

SUMMARY FOR KASAYA PHC


This summary report is based on the findings of the site survey team of EM-ONE on September 1, 2015.

| Secure Empty | Size of available free space | | Building | Number of buildings in | Height of tallest |
|-------------------------------------|------------------------------|-------|-----------------|-------------------------------|-------------------|
| Space | L (m) | B (m) | Shading | PHC | building (m) |
| Yes | 45 | 43 | No | 7 | 5 |
| Telecommunication network available | | | Site Topography | | |
| AIRTEL/ETISALAT | | | FLAT SURFAC | CE /WITH SANDY-LO OBSERVED | DAMY SOIL |

Notes:

- 1. This PHC has no boundary wall.
- 2. Available space used for farming.

- 1. Boundary wall must be completed for security of installations.
- 2. Available space must be cleared for systems to be installed.



SUMMARY FOR KURMIN KOGI PHC


This summary report is based on the findings of the site survey team of EM-ONE on September 1, 2015.

| Secure Empty Space | Size of available free space | | Building | Number of buildings in | Height of tallest |
|-------------------------------------|------------------------------|-------|--------------|------------------------|-------------------|
| | L (m) | B (m) | Shading | PHC | building (m) |
| No | 14 | 10 | No | 3 | 4 |
| Telecommunication network available | | | | Site Topography | |
| ETISALAT | | | FLAT SURFACE | /WITH SANDY SOI | L OBSERVED |

Notes:

- 1. Overhead lines will cause obstruction for vehicles accessing the PHC.
- 2. High rise buildings may cause shading in available space.
- 3. The ETISALAT telecommunication has poor reception.

- 1. Overhead powerlines will need to be relocated or raised higher for heavy vehicle passage to the
- 2. Alternative to ETISALAT telecommunication network must be sourced.



SUMMARY FOR KURMIN BIPHC

This summary report is based on the findings of the site survey team of EM-ONE on September 1, 2015.


| Secure Empty | Size of available free space | | Building | Number of buildings in | Height of tallest |
|-------------------------------------|------------------------------|-------|--|------------------------|-------------------|
| Space | L (m) | B (m) | Shading | PHC | building (m) |
| Yes | 52 | 17 | No | 2 | 3.5 |
| Telecommunication network available | | | Site Topography | | |
| MTN/AIRTEL/GLO/ETISALAT | | | FLAT SURFACE /WITH SANDY-LOAM SOIL OBSERVED | | OAM SOIL |

Notes:

1. This PHC has no boundary wall.

Recommendations:

1. Boundary wall must be constructed to secure the installations and PHC.



SUMMARY FOR LIKORO PHC


This summary report is based on the findings of the site survey team of EM-ONE on September 1, 2015.

| Secure Empty Space | Size of available free space | | Building | Number of buildings in | Height of tallest |
|---------------------------------------|-------------------------------------|-------|--------------|------------------------|-------------------|
| | L (m) | B (m) | Shading | PHC | building (m) |
| Yes | 47 | 16 | Yes | 4 | 5 |
| Telecommu | Telecommunication network available | | | Site Topography | |
| STARCOMS/AIRTEL/GLO/ETISALAT/VISAFONE | | | FLAT SURFACE | /WITH SANDY SOI | L OBSERVED |

Notes:

- 1. PHC entrance gate is narrow.
- 2. Neighbouring boundary wall will cause obstructions for vehicles to the site.

- 1. PHC entrance gate must be expanded.
- 2. Neighbouring boundary wall must be broken down and reconstructed to allow trucks to move into the PHC.



SUMMARY FOR MADAKIYA PHC

This summary report is based on the findings of the site survey team of EM-ONE on September 1, 2015.


| Secure Empty Space | Size of available free space | | Building | Number of buildings in | Height of tallest |
|-------------------------------------|------------------------------|-------|--------------|------------------------|-------------------|
| | L (m) | B (m) | Shading | PHC | building (m) |
| Yes | 32 | 19 | No | 3 | 4.4 |
| Telecommunication network available | | | | Site Topography | |
| MTN/AIRTEL/GLO/ETISALAT | | | FLAT SURFACE | /WITH SANDY SOI | L OBSERVED |

Notes:

1. This PHC has no boundary wall.

Recommendations:

1. Boundary wall must be constructed to installations and PHC.



SUMMARY FOR MAH PHC


This summary report is based on the findings of the site survey team of EM-ONE on September 1, 2015.

| Secure Empty | Shadina | Number of buildings in | Height of tallest | | |
|--------------|------------------|------------------------|-------------------|-----------------|--------------|
| Space | L (m) | B (m) | Shading | PHC | building (m) |
| Yes | 39 | 26 | No | 1 | 5 |
| Telecommu | unication networ | k available | Site Topography | | |
| | GLO/ETISALAT | | FLAT SURFACE | /WITH SANDY SOI | L OBSERVED |

Notes:

1. Available space needs further observation.

MAH PHC LAYOUT



| CLIE | ENT: | | | | | | | | |
|-----------------|-------|--------|----------------|---------|--------------------|---------------|-------------|--------|---------------|
| | PF | ROJI | ECT NAM | 1E | KAD | UI | NA SO | LAR | PROJECT |
| က | RE | FEF | RENCE D | RAWING: | | | | | |
| DRAWING DETAILS | DF | RAW | ING NO: | | | | | | |
| VING | П | TLE | : | | MAH PHC | L | AYOUT | | |
| DRA | - | | RIPTION | : | | | | | |
| | - | RAV | VN: KED BY: | | | | | | |
| | - | ATE | | | Sent | | 2015 | | |
| | NO | | NAME | | Бере | 1 | DAT | E | |
| SN | A | | | | | 1 | | | |
| REVISIONS | В | | | | | | | | |
| 22 | С | | | | | 4 | | | |
| | D | | | | | | | | _ |
| SHE | ET NC |): | | 1 | TOTAL | SH | IEETS: | | 1 |
| LEGI | END: | | | ТТ | | | | | |
| LEGI | END: | | | | EGEN | | | | |
| LEGI | END: | | | LIBH | EGEN BOI HOI | R.I | Е | | |
| LEGI | END: | | | | BOI | RI LI | E E | | |
| LEGI | END: | | | | BOI HOI | RI LI E | E E | | |
| LEGI | END: | | | | BOI HOI TRE | RI LI E | E E | | |
| APPROVAL BD | END: | | APPROVE | BH T1 | BOI HOI TRE | RI LI E | E E L | OVED V | WITH COMMENTS |

SIGNATURE / STAMP

DATE:

SUMMARY FOR MANCHOK PHC

This summary report is based on the findings of the site survey team of EM-ONE on September 1, 2015.


| Secure Empty | Chadina | Building | Number of buildings in | Height of tallest | |
|--------------|------------------|-------------|------------------------|-------------------|--------------|
| Space | L (m) | B (m) | Shading | PHC | building (m) |
| Yes | 30 | 19 | No | 5 | 3.6 |
| Telecommu | unication networ | k available | | Site Topography | |
| MTN/ | AIRTEL/GLO/ETIS | ALAT | FLAT SURFACE | /LOAMY CLAY SOI | L OBSERVED |

Notes:

1. This PHC has no boundary wall.

Recommendation:

1. Boundary wall must be constructed to secure PHC and installation.



SUMMARY FOR MARO PHC

This summary report is based on the findings of the site survey team of EM-ONE on September 1, 2015.


| Secure Empty | Size of availal | ble free space | Building | Number of buildings in | Height of tallest |
|--------------|------------------|----------------|-----------------------------|------------------------|-------------------|
| Space | L (m) | B (m) | Shading | PHC | building (m) |
| Yes | 55 | 23 | No | 2 | 5 |
| Telecommu | ınication networ | k available | | Site Topography | |
| AIR | RTEL/GLO/ETISAL | ΑT | FLAT SURFACE /LOAMY SOIL OB | | DBSERVED |

Notes:

1. Trees south of the PHC will cause shading of the installation.

Recommendation:

1. Proposed solar system installation must be positioned away from the trees or have the trees cut down.




SUMMARY FOR RAFIN GUZA PHC

This summary report is based on the findings of the site survey team of EM-ONE on September 1, 2015.

| Secure Empty | Size of availa | ble free space | Building Shading | Number of buildings in | Height of tallest |
|--------------|------------------|----------------|-----------------------------|------------------------|-------------------|
| Space | L (m) | B (m) | | PHC | building (m) |
| Yes | 24 | 17 | No | 2 | 3.5 |
| Telecommu | unication networ | k available | | Site Topography | |
| MTN/ | AIRTEL/GLO/ETIS | ALAT | FLAT SURFACE /LOAMY SOIL OF | | DBSERVED |

Notes:



SUMMARY FOR RIMIN DOKO PHC

This summary report is based on the findings of the site survey team of EM-ONE on September 1, 2015.


| Secure Empty | Chadina | Building | Number of buildings in | Height of tallest | |
|--------------|------------------|-------------|------------------------|-------------------|--------------|
| Space | L (m) | B (m) | Shading | PHC | building (m) |
| No | 25 | 14 | No | 3 | 4.5 |
| Telecommu | unication networ | k available | | Site Topography | |
| | ETISALAT | | FLAT SURFA | ACE /LOAMY SOIL C | DBSERVED |

Notes:

- 1. Overhead concrete obstructions at the entrance gate will prevent heavy trucks from gaining access to the PHC.
- 2. A tree that will cause obstruction and shading is in the available space.

Recommendations:

- 1. Overhead concrete obstructions must be broken down and reconstructed to allow heavy vehicles to access the PHC.
- 2. The tree located in the available space will have to be cut down and uprooted.



SUMMARY FOR RUZIA PHC

This summary report is based on the findings of the site survey team of EM-ONE on September 1, 2015.


| Secure Empty | Chadina | Building | Number of buildings in | Height of tallest | |
|--------------|------------------|-------------|------------------------|-------------------|--------------|
| Space | L (m) | B (m) | Shading | PHC | building (m) |
| No | 54 | 50 | No | 1 | 5 |
| Telecommu | unication networ | k available | | Site Topography | |
| N | MTN/AIRTEL/GLO | | FLAT SURFA | ACE /LOAMY SOIL C | DBSERVED |


Notes:

- 1. This PHC has no boundary wall
- 2. Airtel telecommunication service is poor.

Recommendations:

1. Boundary wall must be constructed to secure PHC and installation.





SUMMARY FOR TASHEN KADE PHC

This summary report is based on the findings of the site survey team of EM-ONE on September 1, 2015.


| Secure Empty | Size of availa | railable free space Building | Number of buildings in | Height of tallest | |
|--------------|------------------|------------------------------|------------------------|-------------------|--------------|
| Space | L (m) | B (m) | Shading | PHC | building (m) |
| Yes | 30 | 14 | No | 2 | 4 |
| Telecommu | unication networ | k available | | Site Topography | |
| MTN/ | AIRTEL/GLO/ETIS | ALAT | FLAT SURFA | ACE /SANDY SOIL C | BSERVED |

Notes:

1. This PHC has no boundary wall

Recommendations:

1. Boundary wall must be constructed to secure PHC and installation.



SUMMARY FOR TELEVISION GARAGE PHC

This summary report is based on the findings of the site survey team of EM-ONE on September 1, 2015.

| Secure Empty | Size of availal | ble free space | Building Shading | Number of buildings in | Height of tallest |
|--------------|------------------|----------------|---------------------|------------------------|-------------------|
| Space | L (m) | B (m) | | PHC | building (m) |
| Yes | 17 | 10 | No | 6 | 5 |
| Telecommu | unication networ | k available | | Site Topography | |
| | | | FLAT SURF | ACE /SANDY SOIL C | BSERVED |

Notes:

1. This PHC contains access problems for heavy vehicles.

SUMMARY FOR TURAWA PHC

This summary report is based on the findings of the site survey team of EM-ONE on September 1, 2015.


| Secure Empty Size of available | ole free space | Building | Number of buildings in | Height of tallest | |
|--------------------------------|------------------|-------------|------------------------|-------------------|--------------|
| Space | L (m) | B (m) | Shading | PHC | building (m) |
| No | 30 | 19 | Yes | 1 | 5 |
| Telecommu | ınication networ | k available | | Site Topography | |
| MTN | | FLAT SURF | ACE /SANDY SOIL C | BSERVED | |

Notes:

1. Available space is limited

Recommendations:

1. This PHC must be re-visited for another assessment.



SUMMARY FOR ZANGON AYA PHC

This summary report is based on the findings of the site survey team of EM-ONE on September 1, 2015.


| Secure Empty | Size of availal | e of available free space Building Shading | Building | Number of buildings in | Height of tallest |
|--------------|------------------|---|------------|------------------------|-------------------|
| Space | L (m) | B (m) | Shading | PHC | building (m) |
| Yes | 36 | 15 | No | 7 | 5 |
| Telecommu | unication networ | k available | | Site Topography | |
| | AIRTEL/ETISALAT | | SLOPY SURF | ACE /SANDY SOIL (| DBSERVED |

Notes:

1. Overhead powerlines obstruct the access road to the PHC.

Recommendations:

1. Obstructing overhead powerlines must be raised higher or relocated for movement of heavy vehicles making deliveries to the PHC.



SUMMARY FOR MAKARFI PHC

This summary report is based on the findings of the site survey team of EM-ONE on September 1, 2015.

| Secure Empty | Size of availal | e of available free space Building Shading | Building | Number of buildings in | Height of tallest |
|--------------|------------------|---|---------------------------|------------------------|-------------------|
| Space | L (m) | B (m) | Shading | PHC | building (m) |
| No | 14 | 12 | Yes | 3 | 4 |
| Telecommu | unication networ | k available | | Site Topography | |
| MTN/ | GLO/AIRTEL/ETIS | ALAT | SLOPY SURFACE /SANDY SOIL | | OBSERVED |

Notes:

1. Available space has no boundary wall and is surrounded by built up areas.

Recommendations:

1. Excessive buildings may have to be used as equipment housing or demolished.

